

## Product sheet

# Analog output module 2 channels isolated 15 bits

Brand: SCHNEIDER

Reference: IMPO BMXAMO0210



2-channel analog output module for Modicon X80 system, with galvanic insulation between channels and earth. It supports current signals 0...20 mA and 4...20 mA, as well as voltage  $\pm 10$  V.

[View product online](#)

## Description

2-channel analog output module for Modicon X80 system, with galvanic insulation between channels and earth. Designed for industrial applications, it allows to configure each channel as a current output (0...20 mA, 4...20 mA) or voltage ( $\pm 10$  V), with 15 bit resolution + signal.

## Specifications

|                     |                                                                                                    |
|---------------------|----------------------------------------------------------------------------------------------------|
| EAN                 | 3595863910209                                                                                      |
| Manufacturer        | SCHNEIDER                                                                                          |
| Range               | Industrial                                                                                         |
| # Elements          | 2                                                                                                  |
| Weight (kg)         | 0,144 kg                                                                                           |
| Power (W)           | 2,1 W (24 V cc típico), 2,8 W (24 V cc máximo), 0,35 W (3,3 V cc típico), 0,48 W (3,3 V cc máximo) |
| Protection          | IP20                                                                                               |
| Nominal voltage (V) | 24 V CC                                                                                            |

This document is based on the product page published in our store and is provided for information only. It is not contractual. It may contain errors or omissions and does not replace the manufacturer datasheet.

[If you have any questions, contact our support team](#)