

## Product sheet

## ACTI 9 32A 30mA 1 pole type C differential switch for electrical protection.



Brand: SCHNEIDER

Reference: IMPO A9DE3632

The ACTI 9 iCV40N 1PN C 32A 30mA AC RCBO is an electrical protection device that combines a residual current device (RCD) and a circuit breaker. Designed to ensure safety in electrical installations, it offers protection against overloads and short circuits.

[View product online](#)

### Description

The ACTI 9 iCV40N 1PN C 32A 30mA AC RCBO is an electrical protection device designed to ensure safety in residential and industrial electrical installations. This combination residual current device (RCBO) offers effective protection against overloads and short circuits, as well as rapid disconnection in case of current leakage, making it a comprehensive solution for electrical circuit protection. Its compact design allows for easy installation in electrical panels, optimizing space and facilitating maintenance. Furthermore, its advanced technology ensures reliable and long-lasting operation, complying with current safety regulations.

- **Type:** RCBO (Combined Residual Current Circuit Breaker)
- **Rated Current:** 32A
- **Leakage Current:** 30mA
- **Phases:** 1PN (single-phase)
- **Protection:** Overload and short circuit
- **Standards:** Complies with electrical safety regulations
- **Dimensions:** Compact for easy installation
- **Use:** Suitable for residential and industrial applications
- **Brand:** Schneider Electric
- **Reference:** iCV40N

### Specifications

|                   |               |
|-------------------|---------------|
| Rated current (A) | 32            |
| Sensitivity       | 30 mA         |
| Curve             | C             |
| EAN               | 3606489444266 |

|              |                    |
|--------------|--------------------|
| No. of poles | 1P+N               |
| Reference    | SCHNEIDER A9DE3632 |

This document is based on the product page published in our store and is provided for information only. It is not contractual. It may contain errors or omissions and does not replace the manufacturer datasheet.

[If you have any questions, contact our support team](#)

Item downloaded on 29 September 2026